



**COSUMNES COMMUNITY SERVICES DISTRICT  
FIRE DEPARTMENT**

8820 Elk Grove Blvd. Elk Grove, CA 95624

(916) 405-7100

[CosumnesCSD.gov/Fire](http://CosumnesCSD.gov/Fire)

## **FIRE PREVENTION CONSTRUCTION STANDARDS FIRE EXTINGUISHERS**

Standard Number: FPCS-1006

Original Effective Date: 5/7/2020

Revision Date: 10/16/2023

Code Section: 2022 California Fire Code / CCR Title 19, Division 1

### **STANDARD**

1006.1 Cosumnes Fire Department, Fire Prevention Division ("Division") provides minimum standards requiring all businesses and apartment buildings to install and maintain a minimum of one 2A:10BC-rated fire extinguisher.

### **PURPOSE AND SCOPE**

1006.2 This construction standard details how and where fire extinguishers shall be installed and how they shall be maintained.

1006.3 This standard applies to all businesses and apartment buildings in the City of Elk Grove, the City of Galt, and unincorporated areas of the south portion of Sacramento County within the Cosumnes Community Services District's Fire Department's ("Department") jurisdiction.

### **APPLICATION**

1006.4 All businesses and apartment buildings must install and maintain a minimum of one 2A:10BC rated fire extinguisher, mounted in an approved manner in an approved location (see Exhibit 1). Fire extinguishers shall be mounted so that the top of the extinguisher is between 3 feet and 5 feet from the finished floor.




Exhibit 1:



Fire extinguishers shall not be obstructed or obscured from view. In rooms or areas where visual obstruction cannot be completely avoided, means shall be provided to indicate the locations of extinguishers. Fire extinguishers shall be located in conspicuous locations where they will be readily accessible and immediately available for use. These locations shall be along normal paths of exit travel, preferably near an exit door. The travel distance to an extinguisher shall not exceed 75 feet and must be located on each floor level.

Where extinguishers are subject to malicious use or damage, locked cabinets may be used, provided they allow a means of ready access. The cabinets shall have approved/listed components to ensure the extinguishers are accessible in the event of an emergency. Validation that the cabinets are in compliance will be the responsibility of the servicing company at the time of annual inspection.

## **INSPECTION AND SERVICING**

1006.5 Fire extinguishers must be serviced annually and after each use by a state-certified fire extinguisher technician. A tag must be placed on the fire extinguisher by the technician and must remain on the extinguisher for the fire inspector to view. Additionally, a Service Collar is placed on all stored pressure dry chemical extinguishers at the time of the 'six-year' internal inspection. New fire extinguishers shall have a service tag within 12 months of the date of manufacture. If the date of manufacture is unknown, the extinguisher shall be serviced and tagged when placed in service (see Exhibit 2).



Exhibit 2:



## **REFERENCES**

1006.6 None